G "PULL OUT MAINS CONNECTOR"

H

A

U

R
"PULL"

K

V

S-T

Pull both sides
" ON BOTH SIDES

N

L

J

M

O

P

Q

POWERROD AND MONOBOARD

B

"PUSH"

A   "PUSH"

D

DEMOUNTING OF LOADER

C

A

B

HAS.CD930.DEM-LOADING

REMOVING FLEX FROM CONNECTOR

"PULL"

HAS.CD930.DFM-FLEX

LOADER

PUSH (DISMOUNTING STROKE LIMIT

98

109

113

93

114

145

144

148

149

133

134

116

88

141

115

128

108

104

DETAIL 2

DETAIL 1

DETAIL 1

DETAIL 2

A

B

A

B

A